

# V O L V O

## Volvo Car USA LLC

## Technical Journal

|                                                                                   |                                    |                          |                        |
|-----------------------------------------------------------------------------------|------------------------------------|--------------------------|------------------------|
| Technical Journal Title<br>Propulsion Message with DTC IEM P060700 and/or P061A00 |                                    | Ref. No.<br>TJ 37495.3.0 |                        |
| Issuer (Dept.)<br>Technical Service                                               |                                    | Issue Date<br>6/10/26    | Status Date<br>6/22/26 |
| Car Market<br>United States and Canada                                            | Partner<br>3 US 7510 Volvo Car USA | Function Group<br>3233   |                        |
| Function Description<br>Electric converter, high voltage                          |                                    | Page<br>Page 1 of 2      |                        |

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

### DESCRIPTION:

\*VST Operation No and "Service" section updates.

If a customer experiences a "Propulsion System Performance" message in the DIM with diagnostic trouble code IEM P060700, often in combination with IEM please follow the instructions under "Service".

### CSC Customer Symptom Codes

| Code | Description                                                                                           |
|------|-------------------------------------------------------------------------------------------------------|
| IV   | Text window and warning symbol/Text message                                                           |
| DL   | Warning lights and chimes/Malfunction Indicator Light ("Check engine" light) indication/no indication |

### DTC Diagnostic Trouble Codes

| Control Module | Code    | Fault Type |
|----------------|---------|------------|
| IEM            | P061A00 | Permanent  |
| IEM            | P060700 | Permanent  |

### Vehicle Type

| Type | Eng | Eng Desc | Sales | Body | Gear | Steer | Model Year | Plant | Chassis range | Struc Week Range |
|------|-----|----------|-------|------|------|-------|------------|-------|---------------|------------------|
| 224  | H6  | BH6PHEV  |       |      |      |       | 2022-2023  |       | -             | 202147-202316    |
| 225  | H6  | BH6PHEV  |       |      |      |       | 2022-2023  |       | -             | 202147-202316    |
| 238  | H6  | BH6PHEV  |       |      |      |       | 2022-2023  |       | -             | 202147-202316    |
| 246  | H6  | BH6PHEV  |       |      |      |       | 2022-2023  |       | -             | 202147-202316    |
| 256  | H6  | BH6PHEV  |       |      |      |       | 2022-2023  |       | -             | 202147-202316    |

## Technical Journal 37495.3.0

---

### SERVICE:

**\*Improved software has been released in version 5.1.9.**

\*Perform a software upgrade according to TJ 31543.

### Abbreviations:

IEM = Inverter Electric Rear Axle Drive Module

DIM = Driver Information Module

### Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, use the corresponding VST OP number stated in this TJ.

Please note that fault tracing is not eligible for separate reimbursement under this TJ. Any fault tracing VST operation numbers will be rejected. Note, that the TJ number must be stated in the repair order text.

### VST Operation Number

| VST Operation Number | Description                  |
|----------------------|------------------------------|
| 98821-3              | Software download acc. to TJ |

### VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use the concern area "Vehicle Report" and the sub-concern area "Support Needed", use function group 3233.