

## Vehicle-specific service

Transaction No.: **2083162/2**

01 PSS Engine: exhaust emissions warning lamp lights up, event memory entry P0299 symptom 34203 - V6 TFSI

Release date: Sep 18, 2026

## Condition

| Model(s)                                                   | Year(s) | VIN Range | Vehicle Specific Equipment                                            |                  |                      |                  |
|------------------------------------------------------------|---------|-----------|-----------------------------------------------------------------------|------------------|----------------------|------------------|
| A5, S5 (FU), Q5, Q5 Sportback, SQ5, and SQ5 Sportback (GU) | 2025    | All       | Engine Code: DWV<br>00A5 - Front sensor for driver assistance systems |                  |                      |                  |
|                                                            |         |           | Software part number                                                  | Software version | Hardware part number | Hardware version |
| A6                                                         | 2026    |           | *                                                                     | 0386             | *85E*.907.217.A*     | *                |

## REVISION HISTORY


| Revision | Date       | Purpose                                   |
|----------|------------|-------------------------------------------|
| 2        | -          | Revised <i>Service</i> (Updated verbiage) |
| 1        | 09/02/2026 | Initial publication                       |

## Customer states:

- Drive system fault, exhaust emissions warning lamp lit up in instrument cluster.
- Slight loss of power is noticeable.

## Workshop findings:

- The following event memory entry and symptom are logged in the engine control unit: P029900 Turbo/Super Charger Underboost – symptom 34203 – static/intermittent.



*Postpone repair*

## Technical Background

Under analysis

## Production Solution

Not applicable.

## Service

Please perform Guided Fault Finding for event memory entry P0299.

If no issues are found, erase the event memory entry and postpone the repair.

A technical measure is currently being analyzed. This analysis is expected to be completed in the 4th quarter of 2026.

Note: The target date communicated here is based on planning and is not binding. During the validation, technical and regulatory approval of measures, there may be delays or hindrances in providing the measure throughout the entire process. This must be taken into account accordingly when communicating with customers.

As a part of the process, create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in Audi Now; *Service | AU-US > Pending Service Solutions (PSS)*.

## Warranty

Replacing parts or attempting repairs will not fix the problem. Unjustified work/replacement parts will be charged back. Invoicing under warranty is not permitted.

|                          |                                                                                                                                                   |           |                                       |
|--------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------------------------------|
| <b>Claim Type:</b>       | <ul style="list-style-type: none"><li>If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.</li></ul> |           |                                       |
| <b>Service Number:</b>   | 2470                                                                                                                                              |           |                                       |
| <b>Damage Code:</b>      | 0055                                                                                                                                              |           |                                       |
| <b>Labor Operations:</b> | GFF / Guided Functions                                                                                                                            | 0150 0010 | See SRT with associated operations    |
|                          | GFF / Guided Functions                                                                                                                            | 0150 0060 | Labor according to the diagnostic log |
| <b>Claim Comment:</b>    | As per TSB 2083162/2                                                                                                                              |           |                                       |

Please note the information on predecessors and items that are included and excluded in the repair operations, as well as any associated tasks.

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty

## Additional Information

All part and service references provided in this TSB (**2083162**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a

retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.