



Connection offline

Vehicle-specific service

Transaction No.: **2083163/1**

01 PSS Engine: exhaust emissions warning lamp lights up, event memory entry P0299 symptom 34203 - V6 TFSI

Release date: Sep 2, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment			
A5, S5 (FU), Q5, Q5 Sportback, SQ5, and SQ5 Sportback (GU)	2026	All	Engine Code: DWV 00A5 - Front sensor for driver assistance systems			
			Software part number	Software version	Hardware part number	Hardware version
A6	2026 – 2027		*	0801	*85E*.907.217.A*	*

Customer states:

- Drive system fault, exhaust emissions warning lamp lit up in instrument cluster.
- Slight loss of power is noticeable.

Workshop findings:

- The following event memory entry and symptom are logged in the engine control unit: P029900 Turbo/Super Charger Underboost – symptom 34203 – static/intermittent.

Technical Background

Under analysis.

Production Solution

Not applicable.

Service

Please postpone repair. A technical measure is currently being analyzed. This analysis is expected to be completed in the 4th quarter of 2026.

Note: The target date communicated here is based on planning and is not binding. During the validation, technical and regulatory approval of measures, there may be delays or hindrances in providing the measure throughout the entire process. This must be considered accordingly when communicating with customers.

As a part of the process, create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in Audi Now; *Service | AU-US > Pending Service Solutions (PSS)*.

Warranty

Replacing parts or attempting repairs will not fix the problem. Unjustified work/replacement parts will be charged back. Invoicing under warranty is not permitted.

Claim Type:	If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2470		
Damage Code:	0055		
Labor Operations:	GFF / Guided Functions	0150 0010	See SRT with associated operations
	GFF / Guided Functions	0150 0060	Labor according to the diagnostic log
Claim Comment:	As per TSB 2083163/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Please note the information on predecessors and items that are included and excluded in the repair operations, as well as any associated tasks.

Additional Information

All part and service references provided in this TSB (**2083163**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.