



# Preliminary Information

PIP5467 Repeat Codes P2096 and P2098

Models

| Brand:                     | Model:                                                                                                                                                                                                                               | Model Years: | VIN: |     | Engine:  | Transmissions: |
|----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|------|-----|----------|----------------|
|                            |                                                                                                                                                                                                                                      |              | from | to  |          |                |
| Chevrolet                  | Corvette                                                                                                                                                                                                                             | 2014 - 2017  | All  | All | 6.2L LT1 | M5U            |
| Involved Region or Country | North America                                                                                                                                                                                                                        |              |      |     |          |                |
| Condition                  | Customers may experience MIL Illumination with a repeat diagnostic codes P2096 P2098. These code can be set when the operator drives in a digital manner when they tap the accelerator pedal (on - off - on -off) to maintain speed. |              |      |     |          |                |
| Cause                      | Unknown at this time                                                                                                                                                                                                                 |              |      |     |          |                |

**Correction:**  
Engineering aware of the issue and working on the fix.  
When the fix becomes available this PI will be updated or changed to a bulletin.

Warranty Information

| Labor Operation                                          | Description                                  | Labor Time |
|----------------------------------------------------------|----------------------------------------------|------------|
| 4081528*                                                 | Retrieve and Clear ECM Codes P2096 and P2098 | 0.3 hr     |
| *This is a unique Labor Operation for Bulletin use only. |                                              |            |

Version History

|          |   |
|----------|---|
| Version  | 1 |
| Modified |   |