



Preliminary Information

PIT5590 Service Driver Assist System Message with B172E stored in history

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2018	All	All	All	All
Buick	Envision	2017 - 2018	All	All	All	All
Buick	Lacrosse	2017 - 2018	All	All	All	All
Cadillac	CT6	2017 - 2018	All	All	All	All
Cadillac	XT5	2017 - 2018	All	All	All	All
Chevrolet	Equinox	2018	All	All	All	All
GMC	Acadia	2017 - 2018	All	All	All	All
GMC	Terrain	2018	All	All	All	All

Involved Country/Region	North America
Additional RPO	N/A
Condition	Customer may comment that they received an intermittent "Service Driver Assist System" DIC message and/or vehicle has a B172E or B172F Code Stored in history in the MSM. B172E or B172F is being set as a phantom code due to an electrical backfeed.
Cause	N/A

Correction:

Do not replace any parts. Explain to customer that Engineering is aware of the issue and a new control module with added diodes to address this phantom code is in development and will be available Q1 2019.

Warranty Information

Labor Operation	Description	Labor Time
7080488	Checking system, clearing codes and discussing with customer	Use Published Labor Operation Time

