



Preliminary Information

PIP5568 Service Engine Soon Light Comes on With All 4 Camshaft Position System Performance DTC's P0011, P0014, P0021 and P0024 Setting.

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2018	All	All	3.6 LFY	All
Buick	LaCrosse	2017 - 2018	All	All	3.6 LGX	All
Buick	Regal	2018	All	All	3.6 LGX	All
Cadillac	ATS	2016 - 2018	All	All	3.6 LGX	All
Cadillac	CT6	2016 - 2018	All	All	3.0 LGW, 3.6 LGX	All
Cadillac	CTS	2016 - 2018	All	All	3.6 LGX	All
Cadillac	XT5	2017 - 2018	All	All	3.6 LGX	All
Chevrolet	Traverse	2018	All	All	3.6 LFY	All
Involved Region or Country		North America				
Condition		Some customers may come in with a MIL/SES illuminated and no drivability concerns.				
Cause		Tech will find P0011, P0014, P021, and P0024 ALL set in the ECM.				

Correction:

If All these codes are found, check to see if TSB [17-NA-317](#) (LFY equipped vehicles only) has been completed and perform that action if it has not been done.

If the bulletin above has been completed or does not apply, clear the codes and return the vehicle to the customer.

At this time the cause for this concern is under investigation.

Please do not replace any parts for the concern at this time.

NOTE: We will update the PI or create a bulletin to replace this PI when more information becomes available.

Version History

Version	1
Modified	Created on 5/7/2018

