



Preliminary Information

PIP5615 DTC P0421 Catalyst 1 Efficiency Below Threshold 1.6 LH7 Diesel

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Equinox	2018		All	All	1.6L Turbo Diesel (LH7)
GMC	Terrain	2018	All	All	1.6L Turbo Diesel (LH7)	All

Involved Region or Country	North America
Condition	Some customers may comment on the service engine soon (SES) light.
Cause	Technicians may find DTC P0421 set in the Engine Control Module (ECM)

Correction:

Perform published diagnostics for DTC P0421, and perform all Bulletins that apply.

If published diagnostics have been performed, and are inconclusive, do NOT replace any parts at this time.

Engineering is aware of this concern and are working on a service update calibration.

Service calibration should be available by February 2019, to address the P0421.

This Preliminary Information will be updated when further information is available.

Version History

Version	1
Modified	12-13-18 - Created

