



Service Bulletin

Bulletin No.: PIE0511

Date: March, 2019

ENGINEERING INFORMATION

Subject: Engineering Information – Service Engine Soon (SES) Light On, DTCs P06C5, P06CC, P066A, P066C, P066E, P067A, P067C, P067E, P068C, P068E, P0671, P1337 and P133F Set

Attention: Proceed with this EI ONLY if the customer has commented about this concern AND the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the EI does not show in GWM/IVH, disregard the PI and proceed with diagnostics found in published service information. THIS IS NOT A RECALL — refer to Service Bulletin 04-00-89-053E for more details on the use of Engineering Information bulletins.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 2500/3500	2019	2019			Equipped with 6.6L Engine (RPO L5P)	
GMC	Sierra 2500/3500						

Involved Region or Country	North America
Condition	Important: If the customer did not bring their vehicle in for this concern, DO NOT proceed with this EI. Some customers may comment on the Service Engine Soon (SES) light on. Technicians may fine the following DTCs set. • P06C5 • P06CC • P066A • P066C • P066E • P067A • P067C • P067E • P068C • P068E • P0671 • P1337 • P133F
Cause	GM Engineering is attempting to determine the root cause of the above condition. Engineering has a need to gather information on vehicles PRIOR to repair that may exhibit this condition. As a result, this information will be used to "root cause" the customer's concern and develop/validate a field fix.

Correction

If you encounter a vehicle with the above concern, clear the codes and perform the glow plug learn procedure. If codes will not clear and learn cycle will not run, call the engineers listed with the results and get further instructions.

Contact Information

Engineer Name	Phone Number
Curtis Tyson	(248) 639-8483

Please include the following information if leaving a message:

- Technician name
- Dealer name and phone number
- Complete VIN and repair order (R.O) number

On the repair order, document the date and time the call was placed (even if the engineer was not reached).

If engineering is unable to return the call within one hour, proceed with diagnosis and repair based on information found in SI.

Warranty Information

If engineer was contacted or required information was provided, use:

Labor Operation	Description	Labor Time
4086768*	Engineering Information – Service Engine Soon (SES) Light On, Multiple P-Code DTCs Set	0.4 hr
* This is a unique labor operation for bulletin use only.		

Version	1
Modified	Released February 25, 2019