

Audi On-car analysis list from December 8, 2025

Please contact Audi Helpline before attempting repair

Please see TSB 2066297 '00 VIN-4-PIN reporting program (V4P, vin4pin) for more info about the program

	Models	MY	Engine	Trans	Topic	Topic details
	A3	2022-2025	any	Any	48V Battery Cooling Fan – P0A8200	Diagnostic LOG uploaded to paperless showing DTC “P0A8200” in DA0021 Pictures during work instructions provided by TAC
	A6, A7, A8, Q7, Q8	2023-2025	any	Any	B&O extendable tweeter	For B&O audio system with extendable/retractable tweeters in dash Tweeter gets stuck or shutters during operation Take a short video duplicating concern Fully extend the tweeter manually, cycle key. Is function restored? Does output diagnosis work correctly? Clear faults and re-evaluate WEB TAC case with documentation provided.
	A5, Q5, A6 e-tron, Q6 (FU, GU, GH, GF)	2025	any	Any	PPE - PPC vehicles time is off by 1 hour	Photo of time in cluster, time settings in MMI, another phone with navigation location and time all in one photo • Read all MVB's from Da0075 while issue is NOT present • Read all MVB's from Da0075 when issue is actively occurring (document the log ID to correspond) • Provide specific location information as to where and how the duplicate • Can this be duplicated on other vehicles? • Is the area of concern close to another time zone? • Please provide an address or GPS location of the area in which the concern happens