



## STAR ONLINE PUBLICATION



**Case Number:** S2609000001

**Release Date:** January 2026

**Symptom/Vehicle Issue:** Diagnostic Trouble Code (DTC) P2482-00 Exhaust Gas Temperature Sensor Circuit High – Bank 1 Sensor 5

**Effected Vehicles:** 2025 RAM Cab Chassis (DD/DP) 2026 RAM Cab Chassis (DD/DP)

**Customer Complaint/Technician Observation:** Technician may find the check engine light (CEL) is illuminated with DTC P2482 setting in the PCM on a 25MY or 26MY Cab Chassis (DD/DP)

**Discussion:** If the normal diagnostics have led to replacement of the number 5 temperature sensor and DTC returns, it is advised to perform and follow the trouble tree diagnostics for DTC P1030-00 Exhaust Gas Temperature Sensor Circuit High – Bank 1 Sensor 7

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**