



Service Bulletin

Bulletin No.: PIP5929G

Date: January, 2026

PRELIMINARY INFORMATION

Subject: Diagnostic Tip for DTC P219A Setting with No Other Drivability Symptoms

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Encore GX	2020 - 2026		All	All	1.2L LIH and LBP	All
Buick	Envista	2024-2026		All	All	1.2 LIH and LBP	All
Chevrolet	Trailblazer	2021 - 2026		All	All	1.2L LIH and LBP	All
Chevrolet	Trax	2024 - 2026		All	All	1.2L LIH and LBP	All

Involved Region or Country	North America
Condition	MIL on with DTC P219A stored as current or history
Cause	Fuel injectors

Correction

If you encounter DTC P219A set as current or in history replace the 3 fuel injectors per Service Information using the latest parts available in EPC.

Once completed clear any remaining DTC's and evaluate the vehicle.

Warranty Information

For vehicles repaired under the Emission coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4022330	Fuel Injector Replacement	Use published time

Version	8
Modified	06/16/2023 - Created. 12/16/2024 Updated Models and RPO code 01/17/2025- Updated Models and RPO code. 03/07/2025 – Updated Models. 08/08/2025- Updated to the Warranty section 10/8/2025- Updated to include 2026 Model Year 10/16/2025- Updated to the warranty, condition, cause and correction sections

