

Vehicle-specific service

Transaction No.: **2081028/2**

93 Reporting Obligation Pre-Repair PHEV "Electrical system malfunction" warning light is on; U01A000, U01A400, U01A700

Release date: Feb 23, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
Q5 e quattro	2021 – 2022	All	DLGA
Q5 e quattro	2023 – 2025		DSMA

REVISION HISTORY

Revision	Date	Purpose
2	-	Revised header (Add Model Years)
1	02/17/2025	Initial publication

Customer states:

- There is an “electrical system malfunction” warning light is on.
- The vehicle will not go into drive.

Workshop findings:

The following DTCs **must** be stored in the Hybrid Battery Management, J840 (address word 008C):

- **P0AF800:** Hybrid/EV Battery System Voltage
- **U01A000:** Lost Communication with Hybrid/EV Battery Interface Control Module "A"
- **U01A100:** Lost Communication with Hybrid/EV Battery Interface Control Module "B"
- **U01A200:** Lost Communication with Hybrid/EV Battery Interface Control Module "C"
- **U01A300:** Lost Communication with Hybrid/EV Battery Interface Control Module "D"
- **U01A400:** Lost Communication with Hybrid/EV Battery Interface Control Module "E"
- **U01A500:** Lost Communication with Hybrid/EV Battery Interface Control Module "F"
- **U01A600:** Lost Communication with Hybrid/EV Battery Interface Control Module "G"
- **U01A700:** Lost Communication with Hybrid/EV Battery Interface Control Module "H"

Technical Background

Various parts have been replaced under warranty for the condition noted above, but no issues were identified with these parts. In an effort to gain information on the DTC codes for the vehicles listed above, we are asking that you

contact the Audi Technical Assistance Center (TAC) before replacing any parts. This will assist us in diagnosing any potential issues with the condition noted above.

Production Solution

No changes to production have been made, as no issue has been identified.

Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition.

Verify the condition.

If the vehicle is within the New Vehicle Limited Warranty, contact a TAC consultant before proceeding. Please attach the DTC and diagnostic log to the TAC Web Ticket.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2081028**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.