

## Technical Service Bulletin (TSB)

### Flash: Body Control Module (BCM) Update

|                    |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |       |                   |                                                                                                                                                                                                                                                                                                  |   |
|--------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|-------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---|
| REFERENCE:         | TSB: 08-074-26<br>GROUP: 08 - Electrical                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | Date: | February 20, 2026 | REVISION:                                                                                                                                                                                                                                                                                        | — |
| VEHICLES AFFECTED: | 2026 (LB) Dodge Charger<br>This bulletin applies to vehicles built on or before November 18, 2025 (MDH 1118XX) equipped with 400V G2500 FR/RR Elec Drive Motors (Sales Code ELD) and without Power Hatch (Sales Code JRC).                                                                                                                                                                                                                                                                                                                          |       |                   | MARKET APPLICABILITY:<br><div><input checked="" type="checkbox"/> NA<input type="checkbox"/> MEA<br/><input type="checkbox"/> SA<input type="checkbox"/> IAP<br/><input type="checkbox"/> EE<input type="checkbox"/> CH</div><br><b>NOTE:</b> This bulletin applies to the North America market. |   |
| CUSTOMER SYMPTOM:  | Customers may comment on the following: <ul style="list-style-type: none"><li>The liftgate will not open when a release button (interior, exterior, or FOB/K) is pressed.</li></ul> <p><b>NOTE:</b> There are no Malfunction Indicator Lamp (MIL) illumination or related messages displaying in the Instrument Panel Cluster (IPC) for this condition.</p> <p>The vehicle may set the following Diagnostic Trouble Code (DTC):</p> <ul style="list-style-type: none"><li>B18AA-11 - Trunk/Gate Unlock Control 1-Circuit Short to Ground.</li></ul> |       |                   |                                                                                                                                                                                                                                                                                                  |   |
| CAUSE:             | BCM software update                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |       |                   |                                                                                                                                                                                                                                                                                                  |   |

#### REPAIR SUMMARY:

This bulletin involves reprogramming the BCM with the latest available software.

#### CLAIMS DATA:

| Labor Operation No: | Labor Description                                   | Skill Category                  | Labor Time |
|---------------------|-----------------------------------------------------|---------------------------------|------------|
| 18-19-02-JP         | Module, Body Control - Reprogram (0 - Introduction) | 6 - Electrical and Body Systems | 0.2 Hrs.   |
| Failure Code        | ZZ                                                  | Service Action                  |            |

#### The dealer must use failure code CC with this Technical Service Bulletin.

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

## DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition above, perform the repair procedure.

## SPECIAL TOOLS/EQUIPMENT:

| Description          | Ref. No. | Notes |
|----------------------|----------|-------|
| wiTECH or Equivalent | —        | —     |

## REPAIR PROCEDURE:

**NOTE:** Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

**NOTE:** If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the BCM with the latest software. If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The helpdesk can be found within the Help menu.
2. Perform an ECU reset. Using the wiTECH, navigate to the Guided Diagnostics menu and select "Reset ECU".
3. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

## POLICY:

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*