



Service Bulletin

Bulletin No.: PIP5934A

Date: March, 2026

PRELIMINARY INFORMATION

Subject: Diagnostic Tip: Possible DTC U060F Or U1346 Set In History Or As Current

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500	2022 - 2023		All	All	2.7 L3B	All
GMC	Sierra 1500	2022 - 2023		All	All	2.7 L3B	All

Involved Region or Country	North America
Condition	DTC U060F or U1346 set as current or in history
Cause	Engineering investigating root cause of condition.

Correction

You may have a vehicle come into the dealer service department with DTC U060F or U1345 set as current or in history.

If a vehicle arrives and only has these 2 DTCs please clear the codes using GDS and confirm they do not reset.

If the codes do reset perform the published SI diagnostics for the failed codes.

Engineering is currently investigating a root cause for this condition.

Do not replace the MAF sensor for this concern.

Version	2
Modified	06/30/2023 - Created on. 03/03/2026- Updated to add 1500 to model list for clarification

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2026 General Motors. All Rights Reserved.