

Audi On-car analysis list from March 25, 2025**Please contact Audi Helpline before attempting repair****Please see TSB 2066297 '00 VIN-4-PIN reporting program (V4P, vin4pin) for more info about the program**

	Models	MY	Engine	Trans	Topic	Topic details
	Q5 PHEV	2024-2025	PHEV	PHEV	Check engine light after charging	Verify the customer concern. Check DTC memory (P0E5E00: BATTERY CHARGER CONTROL MODULE PROCESSOR PERFORMANCE) is stored in the 008C Contact TAC for further direction
	A3	2025	Any	Any	Check engine light	DTC P05A300 and/or P05A000 and/or U058500 Possible on-site analysis Contact TAC for further direction
	Q4	2022-2023	Any	Any	Vehicle sound Malfunction warning	Warning message relating to the sound generator is able to be duplicated TSB PSS 2071352 applies System otherwise works No DTC Potential on-site needed Contact TAC for further steps
	Q5 (GU), A5(FU)	2025	Any	Any	check engine lamp on - P219500	Before performing work on the vehicle proceed as follows: 1.P219500: O2 Sensor Signal Biased/Stuck LeanBank 1 Sensor 1 No Sub Type Information. 2.Contact TAC for further instruction. Possible onsite.