



# Technical Service Bulletin

---

## PSS 91 Lamp warning message, DTC B182700 is stored in the comfort control module

91 20 31 2058435/1 February 3, 2020.

| Model(s) | Year | VIN Range       | Vehicle-Specific Equipment |
|----------|------|-----------------|----------------------------|
| A7       | 2019 | 019206 - 999999 | Not Applicable             |
| A7       | 2020 | All             | Not Applicable             |

## Condition

### Customer states:

- There is a headlight warning displayed in the instrument cluster when using the turn signals. When this occurs, the lighting functions are working properly.

### Workshop findings:

- Lighting functions are working properly.

The following DTC is stored in the comfort control module, J393 (address word 0046):

- **DTC B182700** (feedback of indicator status implausible).

## Technical Background

The software needs to be updated.

## Production Solution

In preparation for the end of Q1.

## Service

1. If the customer's vehicle condition matches the condition listed in the *Workshop findings* of this PSS TSB, explain to the customer that a solution is forthcoming and that no repairs are necessary at this point.
2. Do not replace any components for this condition since this will not resolve the customer's concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*), or through the Technical Assistance Page in Elsa.



# Technical Service Bulletin

---

## Warranty

|                         |                                                                                                                                                                                                                                                     |              |                                                    |
|-------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|----------------------------------------------------|
| <b>Claim Type:</b>      | <ul style="list-style-type: none"><li>• 110 up to 48 Months/50,000 Miles.</li><li>• G10 for CPO Covered Vehicles – Verify Owner.</li><li>• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li></ul> |              |                                                    |
| <b>Service Number:</b>  | 5789                                                                                                                                                                                                                                                |              |                                                    |
| <b>Damage Code:</b>     | 0039                                                                                                                                                                                                                                                |              |                                                    |
| <b>Diagnostic Time:</b> | GFF                                                                                                                                                                                                                                                 | 0151 0000    | Time stated on the diagnostic protocol (Max 30 TU) |
|                         | Road test prior to service procedure                                                                                                                                                                                                                | No allowance | 0 TU                                               |
|                         | Road test after service procedure                                                                                                                                                                                                                   | No allowance | 0 TU                                               |
| <b>Claim Comment:</b>   | As per TSB #2058435/1                                                                                                                                                                                                                               |              |                                                    |

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

All part and service references provided in this TSB (2058435) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.