

**ATTENTION:**

**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

Applicable Vehicles

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Passat	2020	2.0L (DDSB)	All	All	All

Revision Table

Instance Number	Published Date	Version Number	Reason For Update
2058886/1	3/6/2020	21-20-01TT	Original publication.

Technical Background

DTC P0101 sets when Mass Air Flow -**G70**- draw is too high or too low.

DTC	Description
P0101	Mass or Volume Air Flow Sensor "A" Circuit Range/Performance

Service

Pressure test Charge Air System and check for leaks, see Repair Manual Group 21 in Elsa. Look for a loose or a popped out boost hose (Figure 1). Reinstall and secure as needed.



Figure 1

**21-20-01TT - MIL ON, DTC P0101 Mass Air Incorrect Flow****Release date:** 03/6/2020

Additional Information

© 2020Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.