

SSM 48789- 2018-2020 F-150 - 2.7L EcoBoost - Illuminated MIL With DTC P2196 And/Or P2198

Some 2018-2020 Model Year F-150 vehicles equipped with a 2.7L EcoBoost engine may experience an illuminated malfunction indicator lamp (MIL) with DTC P2196 and/or P2198 stored in the powertrain control module (PCM). Engineering is working to implement a solution for this condition. In the interim, clear the DTCs with the appropriate Ford scan tool and schedule a follow-up appointment with the customer for early July 2020. Advise the customer that a repair is expected to be available in June 2020 and that the condition has no effect on vehicle operation or long term durability.