



Preliminary Information

PIC6404A Diagnostic Tip - Service Driver Assist, Steering Assist Reduced Messages, MIL illuminated with P25A2, U0265, U0566 setting

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	CT4	2020	ALL	ALL	ALL	ALL
Cadillac	CT5	2020	ALL	ALL	ALL	ALL

Involved Region or Country	North America
Condition	Service Driver Assist, Steering Assist Reduced Messages, MIL illuminated
Cause	Loss of communication with the FCM, P25A2 (Brake System Control Module Requested Malfunction Indicator Lamp Illumination) U0265 (Lost Communication with Front View Camera - Windshield) U0566 (Invalid Data Received from Front Camera Module

Correction:

Important: N202305180 is now published in regards to "Front Camera Module Reset and Loss of Communication" please review this document for noted concern.

Version History

Version	2
Modified	02/06/2020 - Created on. 09/17/2020 - Updated Correction to refer to N202305180.



GENERAL MOTORS