

STAR ONLINE PUBLICATION

Case Number: S2018000010

Release Date: 09/02/2020

Symptom/Vehicle Issue: Malfunction Indicator Lamp (MIL) Illuminated, Diagnostic Trouble Code (DTC) P2C90 - Crankcase Ventilation System - Hose "A" Disconnected or P04FC -Crankcase Ventilation Performance

Customer complaint/ technician observation: Some customers may experience an intermittent MIL illumination. Technician observed two stored codes setting intermittently DTC's P2C90 - Crankcase Ventilation System - Hose "A" Disconnected or P04FC -Crankcase Ventilation Performance as stored.

Discussion: A preliminary inspection has not revealed any obvious issues. In some cases, the condition appeared after a recent Mopar snorkel kit installation. Review all PCM related TSB's that may include PCM software updates for any of the above faults and update the PCM to the most current software. Test the operation to complete.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found