

STAR ONLINE PUBLICATION

Case Number: S2005000004 Rev C.

Release Date: 09/10/2020

Symptom/Vehicle Issue: C0020-01-ABS PUMP MOTOR CONTROL - GENERAL ELECTRICAL FAILURE

Discussion: Diagnostics for this DTC have been updated. Please review and follow the updated steps. The integrated unit can be serviced as separate components - HCU and module.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found