



Preliminary Information

PIP5766 Diagnostic Tip: Possible DTC P0365 And/Or P0366 Set As Current Or History

[Proactive](#)

[Models](#)

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Malibu	2021	All	All	1.5 LFV	All

Involved Region or Country:	North America
Condition:	DTC P0365 and/or P0366 set as current or in history.
Cause:	Under Investigation complete published SI diagnostics for DTC and repair only if directed.

Correction

If you encounter a vehicle with DTC P0365 and/or P0366 set as current or history clear the trouble codes. Using Service Information operate the vehicle under the conditions for running the DTC's. If the codes return as current, complete the published SI diagnostics for the failed trouble codes and only replace components if instructed by Service Information.

If the codes have not returned then release the vehicle to the customer.

This issue is currently being investigated by GM Engineering.

Warranty Information

For vehicles repaired under the Emission coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation:	Description	Labor Time:
4087718	Complete published diagnostics and clear code if diagnostics lead to no repairs	0.3 Hr.

Version History

Version	1
Modified	11/19/2020 - Creaated on.

