

Special Service Message

NOTE: A Special Service Message is a formal communication issued by Land Rover and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Land Rover technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 75149 - Range Rover L405/L494 AJ20D6 21MY DTC Flagged Incorrectly

Models : Range Rover / L405

Engineer : Skingle Paul

Date Last : 21 DEC 2020 09:20:06

Updated :

Content : Issue : 21MY L405 / L494 AJ20D6 Stop Start (non MHEV) U2300-51 DTC stored in PCM

Cause:

DTCs U2300-51 is currently flagged incorrectly.

Action:

No action required no impact to vehicle and customer. Jaguar LandRover is working on a software fix to resolve DTCs from false flagging, A further communication will be released at that time.

Version : 2