



# Service Bulletin

Bulletin No.: 20-NA-114

Date: December, 2020

## INFORMATION

Subject: Information on False Setting of DTC U0212

| Brand:    | Model:                             | Model Year: |      | VIN: |    | Engine: | Transmission: |
|-----------|------------------------------------|-------------|------|------|----|---------|---------------|
|           |                                    | from        | to   | from | to |         |               |
| Cadillac  | CT4                                | 2020        | 2020 |      |    | All     | All           |
|           | CT5                                |             |      |      |    |         |               |
|           | Escalade                           | 2021        | 2021 |      |    |         |               |
|           | Escalade ESV                       |             |      |      |    |         |               |
| Chevrolet | Corvette (Middle East Export Only) | 2020        | 2020 |      |    |         |               |
|           | Suburban                           | 2021        | 2021 |      |    |         |               |
|           | Tahoe                              |             |      |      |    |         |               |
| GMC       | Yukon                              |             |      |      |    |         |               |
|           | Yukon XL                           |             |      |      |    |         |               |

|                            |                                                                                                                                |
|----------------------------|--------------------------------------------------------------------------------------------------------------------------------|
| Involved Region or Country | North America, China, Europe, Cadillac Korea (South Korea), Middle East                                                        |
| Additional Options (RPOs)  | Vehicles equipped with STEERING COLUMN LOCK-ELECTRICAL (N06)                                                                   |
| Condition                  | Technicians may find DTC U0212 set in the IPC, BCM or CGM.                                                                     |
| Cause                      | The cause of the condition may be that DTC U0212 is a false reading that mapped incorrectly on vehicles equipped with RPO N06. |
| Correction                 | Technician is to ignore DTC U0212 setting and diagnose as DTC U0236.                                                           |

### Parts Information

No parts are normally required for this repair.

### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

| Labor Operation                                          | Description           | Labor Time |
|----------------------------------------------------------|-----------------------|------------|
| 7485998*                                                 | Diagnose as DTC U0236 | 0.3 hr     |
| *This is a unique Labor Operation for Bulletin use only. |                       |            |

|          |                                                                                                                     |
|----------|---------------------------------------------------------------------------------------------------------------------|
| Version  | 2                                                                                                                   |
| Modified | Released May 26, 2020<br>Revised December 04, 2020 – Added Corvette and SUV Models, and Added Warranty Information. |

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION