

On-car analysis list from February 25th, 2021
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Atlas, Atlas Cross Sport	20-21	3.6L (CDVC)	All	MIL-on P0087 P0148 P053F	Customer states MIL-on (Must have P0087, P0148 and/or P053F fault codes) (Untouched vehicles)
Electrical	Atlas, Atlas Cross Sport	19-21	All	All	MFI DTC U019900	Customer states "driver door contact switch error" and/or "electronic parking brake fault" in the MFI (Must have DTC U019900 in the ECM) (Untouched vehicles)
Other	Golf, Golf SportWagen, Jetta GLI	17-19	All	All	Suction Jet Pump	Customer states fuel odor/leak in the rear part of the vehicle (without a punctured fuel tank, hoses or pipes) or difficulty fueling fuel tank or fuel coming back up filler neck (untouched vehicles)