



Technical Service Bulletin

48 Yellow steering malfunction light is on in the cluster, DTC C110DF0 is stored in the active steering module

48 21 00 2061904/2 May 4, 2021. Supersedes Technical Service Bulletin Group 48 number 21-92 dated January 12, 2021 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6 Avant, RS 6 Avant	2021	All	Not Applicable
A6, A7	2019 - 2021	All	Not Applicable
A6 allroad, S6, S7, and RS 7	2020 - 2021	All	Not Applicable
A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, RS 5, RS 5 Cabriolet, RS 5 Sportback, A8, and S8	2018 - 2021	All	Not Applicable
A4, S4, and A4 allroad	2017 - 2021	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Warranty</i> (Added Labor Operation)
1	01/12/2021	Initial publication

Customer states:

- The yellow steering lamp is on in the instrument cluster.

Workshop findings:

- The customer's statement can be reproduced.

The following DTC is stored in the active steering control module, J792 (address word 001B):



Technical Service Bulletin

- **DTC C110DF0** (Active steering safety lock locking failed) with symptom code 13568.

Technical Background

There is a hardware function restriction.

Production Solution

Not applicable.

Service

Install repair kit for steering column lock magnet according to the Elsa repair manual: *Chassis >> Suspension, Wheels, Steering >> 48 Steering >> Steering Column >> Active Steering Safety Lock, Removing and Installing.*

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	4869		
Damage Code:	0016		
Labor Operations:	Steering lock removal + reinstall	4819 1905	See SRT with associated operations
	Vehicle front + rear check	4495 0150	See SRT with associated operations
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU



Technical Service Bulletin

Claim Comment:	As per TSB #2061904/2
-----------------------	-----------------------

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
8W0927289	Repair kit for lock magnet	01

Additional Information

More information on this system can be found in the following resources:

- Elsa: Chassis >> Suspension, Wheels, Steering >> 48 Steering >> Steering Column >> Active Steering Safety Lock, Removing and Installing.

All parts and service references provided in this TSB (2061904) are subject to change and/or removal.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.