



Preliminary Information

PIC6435A Service Adaptive Headlamp Message, Lin Bus DTC U1523 Setting After Right Headlamp Replaced

Models

| Brand:   | Model: | Model Years: | VIN: |     | Engine: | Transmissions: |
|----------|--------|--------------|------|-----|---------|----------------|
|          |        |              | from | to  |         |                |
| Cadillac | XTS    | 2013 - 2014  | All  | All | All     | All            |

|                            |                                                                                            |
|----------------------------|--------------------------------------------------------------------------------------------|
| Involved Region or Country | North America                                                                              |
| Condition                  | Service Adaptive Headlamp message with DTC U1523 setting after right headlamp replacement. |
| Cause                      | Part Issue                                                                                 |

Correction:

Engineering is aware of the concern and is investigating the issue. This PI will be updated when a resolution is available.

Version History

|          |                                                                              |
|----------|------------------------------------------------------------------------------|
| Version  | 2                                                                            |
| Modified | 03/31/2021 - Created on.<br>05/07/2021 - Updated Model Years and Correction. |

