



STAR ONLINE PUBLICATION



Case Number: S2108000128

Release Date: May 2021

Symptom/Vehicle Issue: C151D-00 Tire Pressure Sensor Location Undetermined DTC set

Discussion: Upon scanning the vehicle for DTC's, you may find a C151D-00 Tire Pressure Sensor Location Undetermined set in the RFH. Before performing standard DTC diagnostics, it is recommended to perform the below procedure in an attempt to localize the TPM sensors.

Repair: Remove fuse F49 7.5A from interior PDC located under driver's side dashboard. Wait 5 seconds and reinsert fuse, Clear DTCs. Drive the vehicle to localize the TPM sensor ID's.

Verification: If the TPM sensors do not localize the sensor ID's after a test drive, continue standard diagnostics.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found