



Technical Service Bulletin

40 DTC U112100 stored in the stability control modules 00D4/00D5

40 21 26 2058460/2 August 2, 2021. Supersedes Technical Service Bulletin Group 40 number 20-98 dated February 4, 2020 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8, S8, and A8 PHEV	2020 - 2022	All	Stability control modules

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Added Model Year) Revised <i>Warranty</i> (Added Max TU)
1	02/04/2020	Initial publication

Customer states:

- No customer concerns, it is found during PDI or any other diagnostic work.

Workshop findings:

The following DTC is logged in the stability control module front and stability control module rear, J1152 and J1153 (address word 00D4 and/or 00D5):

- DTC U112100** (data bus missing message (passive/sporadic)) with symptom code 8388618.

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

No repair is necessary. This DTC has no effects on the system characteristics.



Technical Service Bulletin

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	4024		
Damage Code:	0040		
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 30 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2058460/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (2048560) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.