

Reference:

ITB11-034A

Date:

August 4, 2021

**VOLUNTARY SERVICE CAMPAIGN
2009 – 2010 EX35 NO START OR WARNING LIGHT ILLUMINATION
DUE TO WATER IN ELECTRICAL HARNESS**

CAMPAIGN ID #: P1223**APPLIED VEHICLES:** 2009 – 2010 EX35 (J50)

Service Campaign ID # P1223 is no longer active.

- Repair orders opened after this bulletin's published date are no longer eligible for reimbursement under Campaign ID # P1223.
- Discard all previous versions of ITB11-034.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
July 21, 2011	ITB11-034	Original bulletin published
August 4, 2021	ITB11-034A	Bulletin no longer active