



Preliminary Information

PIP5816A P0300 Setting After Bulletin 21-NA-154 Was Performed
Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado	2021	All	All	5.3L L84	10L80 RPO (MQB)
GMC	Sierra	2021	All	All	5.3L L84	10L80 RPO (MQB)

Involved Region or Country	United States, Canada, Mexico, Middle East, Chile, Paraguay, Uruguay, Thailand.
Condition	A customer vehicle may have a concern of a P0300 setting after bulletin 21-NA-154 has been performed.
Cause	Unknown Engineering is looking into this concern.

Correction:

The calibration has been released for this concern, please reference back to [21-NA-154](#).

Note: This is only for vehicle listed above with 5.3L L84 and 10-speed MQB

Version History

Version	2
Modified	07/30/2021 - Created on. 09/27/2021 - Updated Correction Section.

