



Technical Service Bulletin

90 "SAFE CP" is displayed in the Audi virtual cockpit, DTC B200FF0 is stored in the instrument cluster

90 21 32 2065490/1 December 22, 2021.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, S4, A4 allroad, A5, A5 Cabriolet, A5 sportback, S5, S5 sportback, S5 Cabriolet, RS 5, RS 5 sportback, A6, A6 allroad, A6 Avant, S6, RS 6, RS 6 Avant, A7, S7, RS 7, A7 PHEV, A8, S8, A8 PHEV, Q5, SQ5, Q5 PHEV, Q5 sportback, SQ5 sportback, Q7, SQ7, Q8, SQ8, RS Q8, Audi e-tron quattro, and Audi e-tron sportback quattro	2021	All	Audi virtual cockpit Gen2+
Audi e-tron GT, Audi RS e-tron GT	2022	All	Audi virtual cockpit Gen2+

Condition

Customer states:

- "SAFE CP" is displayed in the center of the screen of the Audi virtual cockpit.
- The gauges function normally.

Workshop findings:



Technical Service Bulletin

The following DTC may be stored in the instrument cluster, J285 (address word 0017):

- **DTC B200FF0** (Internal malfunction).

Technical Background

A software malfunction in the instrument cluster may cause the described behavior.

Production Solution

This bulletin will be updated when more information is available. A permanent software solution is currently under development and expected to be available by Q1/2022.

Service

Please replace the instrument cluster, J285 (address word 0017) according to the Elsa Repair Manual.



Note:

As this issue is caused by a software bug, it could, albeit very unlikely, reoccur with the replacement cluster as well.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9025		
Damage Code:	0039		
Labor Operations:	Remove and install/replace dash panel insert	9025 XXXX	See SRT with associated operations
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)



Technical Service Bulletin

	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2065490/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
See ETKA	Instrument cluster	01

Additional Information

All parts and service references provided in this TSB (2065490) are subject to change and/or removal.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.