



Diagnostic Trouble Codes (DTC) P0069-64, P10EC-00, P0191-64 and P240F-00 In Different Combinations, Occurrences, And Time Stamps (Two To Four Codes), Possible Vehicle Derate - US17+OBD16, US17+OBD18 Emissions, Common Model Years 2018 And 2019



> Internal Content

THIS SOLUTION SHOULD ONLY BE FOLLOWED IF TWO OR MORE OF THE LISTED FAULT CODES ARE PRESENT.

If only one of the DTCs is present on the DTC Readout, Guided Diagnostics should be followed as normal.

If a vehicle presents with a combination of between two and four of the relevant DTCs and the listed possible conditions and there are no other symptoms to indicate another issue:

- Replace the external Engine Wiring Harness.

This solution will be updated when further information is available.

 Tags

[k33593604](#) [p0069-64](#) [p0191-64](#) [p10ec-00](#)
[p240f-00](#) [p006964](#) [p019164](#) [p10ec00](#)
[p240f00](#) [mack](#) [volvo](#)

 Live UI **ed links and attachments**

No links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article