



Technical Service Bulletin

91 ConBox High: Bluetooth is not available, DTC U110300 is stored in the telematics control module

91 22 82 2064818/2 March 3, 2022. Supersedes Technical Service Bulletin Group 91 number 21-41 dated October 13, 2021 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8, A8 e quattro, S8, Q5, Q5 e quattro, Q5 Sportback, SQ5, and SQ5 Sportback	2021	All	Not Applicable
A4, A4 allroad, S4, A5, A5 Cabriolet, A5 Sportback, RS 5, S5, S5 Cabriolet, S5 Sportback, RS 5 Sportback, A6, A6 allroad, S6, RS 6 Avant, A7, A7 e quattro, S7, RS 7, e-tron Sportback quattro, e-tron quattro, Q7, SQ7, Q8, SQ8, and RS Q8	2021 – 2022		
e-tron GT, and RS e-tron GT	2022		

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Add Model Year 2022)
1	10/13/2021	Initial publication



Technical Service Bulletin

Customer states:

- It is not possible to establish a Bluetooth connection between a phone and the vehicle.
- The following message is displayed on the MMI display: "The selected system is currently not available."

Workshop findings:

The following DTC may be stored in the telematics control module, J949 (address word 0075):

- **DTC U110300** (Production mode active).

Technical Background

Not Applicable.

Production Solution

Not Applicable.

Service

Please perform the control module replacement test plan for the telematics control module, J949 (address word 0075) via ODIS Guided Functions **without replacing the control module**.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9145		
Damage Code:	0039		
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)
	Road test prior to the service procedure	No allowance	0 TU



Technical Service Bulletin

	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2064818/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2064818) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.