



Subject		Market
MIL ON w/DTC P013A		USA
Service Category	Section	
Vehicle Interior	Meter/Gauge/Display	
Applicability		
2022 IS500, RC F		

APPLICABLE VEHICLES

2022	IS500	2022	RC F
------	-------	------	------

CONDITION

Customers may complain of a MIL ON condition. DTC P013A may be retrieved from the engine ECM:

- P013A – *Oxygen Sensor Slow Response – Rich to Lean Bank 1 Sensor 2*

RECOMMENDATIONS

- Block the exhaust outlets and check for exhaust leaks between the LH exhaust manifold and front exhaust pipe.
- Create a TAS case.
- Perform an All-Data Health Check and attach the Techstream file to the TAS case.

If diagnosis occurs on a holiday or weekend, continue with diagnosis and repair. Save all parts and Techstream file. Contact TAS at the next opportunity.

Note: Exhaust gaskets are non-reusable parts and should be replaced if the exhaust system is disassembled.

LINK REFERENCES

This Tech Tip does not contain any link references