

TECHNICAL SERVICE BULLETIN

Classification:

FE22-002

Reference:

ITB22-015

Date:

April 5, 2022

SERVICE INFORMATION FOR FUEL GAUGE INACCURATE WITH DTCS STORED IN ECM

APPLIED VEHICLES: 2016-2022 Infiniti

SERVICE INFORMATION

If a fuel level sensor has been diagnosed as sending an incorrect level signal, and one or more of the following DTCs are stored in the ECM, do not replace the entire "Fuel Level Sensor Unit, Fuel Filter and Fuel Pump Assembly" (fuel pump assembly). The fuel level sensor can be replaced separately.

- **P0460** (FUEL LEV SEN SLOSH)
- **P0461** (FUEL LEVEL SENSOR)
- **P0462** (FUEL LEVL SEN/CIRC)
- **P0463** (FUEL LEVL SEN/CIRC)

NOTE: Warranty claims referring to fuel level issues that result in the replacement of the entire fuel pump assembly will be charged back.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
April 5, 2022	ITB22-015	Original bulletin published

Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.