



Technical Service Bulletin

43 DTC U112100 stored in the suspension control unit - J775

43 22 61 2067283/1 June 9, 2022.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron GT, and RS e-tron GT	2022 – 2023	All	Not Applicable

Condition

Customer states:

No customer concerns, it is found during PDI or any other diagnostic work.

Workshop findings:

The following DTCs are logged in J775 suspension control unit (diagnostic address 0074):

- U112100 Data bus missing message_(active/static symptom code 262222).
- U112100 Data bus missing message_(active/static symptom code 262256).
- U112100 Data bus missing message_(active/static symptom code 262258).

Technical Background

Not applicable.

Production Solution

Not applicable.



Technical Service Bulletin

Service

If only the DTCs described above are logged in address 0074, do not perform any repair work.

These DTCs have no effects on the suspension system.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (2067283) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.