



NUMBER: 08-109-22

GROUP: 08 - Electrical

DATE: May 19, 2022

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

SUBJECT:

Air Suspension Control Module (ASCM) Updates For Diagnostic Trouble Code (DTC) U0300-00

OVERVIEW:

This bulletin involves informing the technician about reprogramming the ASCM with the latest available software after replacement of the new ASCM only.

MODELS:

2021 - 2022 (WL) Jeep Grand Cherokee

NOTE: This bulletin applies to vehicles within the following markets/countries: North America and EMEA.

NOTE: This bulletin applies to vehicles equipped with Quadra-Lift[®]™ Air Suspension (Sales Code SER).

SYMPTOM/CONDITION:

The replacement ASCM will set DTC:

- U0300-00 - Internal Control Module Software Incompatibility-

DISCUSSION:

If U0300-00 DTC is present, active or stored after a new module replacement, the module must be flashed with the latest available software.

POLICY:

Information Only