



DTC U012100 - Lost Communication With Anti-Lock Brake System (ABS) Control Module, No Additional Information



> Internal Content

Fault Code U012100 may be caused by caused by poor ground connection.. If DTC is present do the following:

1. Disconnect the battery.
2. Remove all exterior Ground conections.
3. Thoroughly clean all surfaces.
4. Reassemble connections.
5. Apply protective coating.

Clear faults and verify the repair. If the fault returns continue with Guided Diagnostics.



Tags

[x209](#)

[u012100](#)

[mack](#)

[ground junction](#)

[volvo](#)

Related links and attachments

No links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article