

GPOP - Issue Review System

Part Number: 68494302A\$, 68509635A\$, 68494303A\$, 68509634A\$, 68494304A\$, 68509625A\$, 68334977A\$, 68504022A\$

Part Description: AXLE ASSEMBLY, Rear Complete

Issue Description: On dual rear wheel high output trucks displaying wheel speed DTCs C003A-2F RR WSS or C0037-2F LR WSS, but for which diagnostics are not finding any hardware problems, and for which the customer narrative includes comments about driving on highway rumble strips, please do not replace the axle, wheel speed sensors, harness, and/or ABS module.

Engineering is working to determine a root cause, please clear the codes and encourage the driver to avoid rumble strips until a repair becomes available. If this issue does not describe your concern, please proceed with repair.

~ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
