



STAR ONLINE PUBLICATION



Case Number: S2121000007

Release Date: April 2021

Symptom/Vehicle Issue: Malfunction Indicator Lamp (MIL) Illuminated. Diagnostic Trouble Code (DTC) P076A – SC Solenoid Circuit, Set.

Discussion: Some customers may experience a MIL illumination. Upon investigation, a technician may find DTC P076A set.

If you receive a vehicle with the above DTC, perform all normal published diagnostics for the DTC. If diagnostics point to a transmission solenoid pack, do not replace the entire valve body assembly to repair this DTC. Only replace the solenoid pack.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found