

GPOP - Issue Review System

Part Number: 68442477A\$, 68442478A\$, 68404410A\$, 68382348A\$, 68262200A\$

Part Description: Module, Anti-lock brake system / Hydraulic Control Unit

Issue Description: Some 2018-19 WD/WK vehicles have the brake lights staying on without depressing the brake pedal as an affect of DTC C1093-62 occurring or due to an internal failure in the HCU/ABS Module please contact FCA Redacted Content.

If there is no response within 15 minutes of initiating your call, please

- Obtain a vehicle scan report with the diagnostic environmental data.
- Record the Primary Pressure Sensor value (\$2002) and the Primary Pressure Sensor offset (\$2007).
- then, continue with your normal diagnostic process.