

GPOP - Issue Review System

Part Number: 68404545A\$

Part Description: SENSOR, Wheel Speed

Issue Description: Please call *FCA Redacted Content* prior to replacing a rear wheel speed sensor for one of the following fault codes:

C003A-1D and or 2F (right rear wss circuit current out of range or signal erratic)
C0037-1D and or 2F (left rear wss circuit current out of range or signal erratic)

If no response in 15 minutes, proceed with repair.

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
~

