



STAR ONLINE PUBLICATION



Case Number: S2008000191

Release Date: 11/26/2020

Symptom/Vehicle Issue: Check Engine Lamp On, P1300 Crankshaft Position Learn Out of Range And P0300 Multiple Cylinder Misfire

Customer Complaint/Technician Observation: Customer complaint check engine lamp turns on within the cluster intermittently. Technician observed two codes, P1300 Crankshaft Position Learn Out of Range and P0300 Multiple Cylinder Misfire.

Repair Procedure: With both DTC's setting, inspect the harness connector at the crankshaft position sensor for any signs corrosion and to ensure that the connector is secure Fig 1, 2.




Fig 1

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found



STAR ONLINE PUBLICATION





Fig 2, Example signs of corrosion

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found