



Preliminary Information

PIT5948 Service Trailer Brake Message With DTC C159C

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade Models	2022	6/10/2022	EOP	All	All
Chevrolet	Silverado 1500 New (RPO J22, VIN Digit 5 = A or D)	2022	11th VIN Digit Z: 7/12/2022, G: 6/30/2022, or 1: 6/27/2022	EOP	All	All
Chevrolet	Suburban	2022	6/10/2022	EOP	All	All
Chevrolet	Tahoe	2022	6/10/2022	EOP	All	All
GMC	Sierra 1500 New (RPO J22, VIN Digit 5 = H or U)	2022	11th VIN Digit Z: 7/12/2022, G: 6/30/2022, or 1: 6/27/2022	EOP	All	All
GMC	Yukon Models	2022	6/10/2022	EOP	All	All

Involved Region or Country	North America
Additional Options (RPO)	RPO JL1
Condition	Some customers may comment when they connect a trailer to the truck that there is a Service Trailer Brake message displayed in the DIC. When checking for DTCs a C159C sym49 maybe set for the Trailer Brake Control Switch.
Cause	Unknown

Correction:

GM Engineering is aware of the issue and working on a fix. When more information is available this PI will be updated.

Version History

Version	1
Modified	09/27/2022 - Created on.



GENERAL MOTORS