



Preliminary Information

PIP5888A 3.0L LM2 Diesel setting DTC P2C7A

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 New (RPO J22, 12th VIN Digit = 5 or greater)	2022	All	All	LM2	All
GMC	Sierra 1500 New (RPO J22, 12th VIN Digit = 5 or greater)	2022	All	All	LM2	All

Involved Region or Country:	North America (including Canada)
Condition:	Some 2022 model year Silverado/Sierra pick up trucks may set a P2C7A.
Cause:	ECM calibration.

Correction:

Reprogram the ECM and perform the fuel injection small quantity data reset. If the code returns, refer to SI.

Version History

Version	2
Modified	10/19/2022 - Created on. 11/01/2022 - Modified to advise the technician to reprogram the ECM for a P2C7A.

