

STAR ONLINE PUBLICATION

Case Number: S2008000097

Release Date: 07/03/2020

Symptom/Vehicle Issue: ESC Cluster Warning Lamp On, DTC B1783-01 Stop Lamp Control Circuit General Failure

Customer Complaint/Technician Observation: Owner complains the ESC (Electronic Stability Control) warning lamp is on. Condition may have appeared after a recent service operation. Technician observed the lamp on with DTC B1783-01 Stop Lamp Control General Failure setting in the ABS module.

Repair Procedure: Inspect the up-fitter accessory 2 wiring take out for proper harness routing or signs of routing damage in the harness take out general location Fig 1, 2.




Fig 1

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

STAR ONLINE PUBLICATION




Fig 2

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found