

SSM 51297

2020-2023 Explorer/Aviator/Police Interceptor Utility - Hybrid - Illuminated MIL With DTC P2D40 - Updated Workshop Manual (WSM) Diagnostics

Some 2020-2023 Explorer/Aviator/Police Interceptor Utility vehicles equipped with a hybrid powertrain may exhibit an illuminated malfunction indicator lamp (MIL) with diagnostic trouble code (DTC) P2D40. This may be due to the high voltage battery thermal system not cooling as it should. Follow the updated WSM Section 414-03 including listed possible sources, visual inspection and prechecks, and diagnostic procedures.