



STAR ONLINE PUBLICATION



Case Number: S2308000010

Release Date: January 2023

Symptom/Vehicle Issue: Body Control Module (BCM) Setting a U1190-00 Lost Communication with Humidity Sensor

Discussion: Upon a remote start event the BCM will set Diagnostic Trouble Code U1190-00 - Lost Communication with Humidity Sensor. The DTC will be active during the remote start event and move to a stored state after the remote start event. Do not replace any components for this concern, the DTC has no affect on system operation and the DTC can be cleared. If the DTC is set other than with a remote start, use normal diagnostics in Service Library.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found