

Subject		Market	
22-24 MY Vehicles MIL On, P26CA14, P26CA31		USA	
Service Category		Section	
Engine/Hybrid System		Cooling	
Applicability			
22-24 MY A25A Vehicles			

APPLICABLE VEHICLES

2022-2023	Highlander HV	2022-2024	RAV4
2022-2024	Camry	2022-2024	RAV4 HV
2022-2024	Camry HV	2022-2023	Sienna HV

CONDITION

Some 2022-2024 MY vehicles equipped with the A25A engine may exhibit a leak from the engine water pump, and/or MIL On condition accompanied by DTC(s):

- P26CA14 *Engine Coolant Pump Circuit Short to Ground or Open*
- P26CA31 *Engine Coolant Pump No Signal*

RECOMMENDATIONS

If the vehicle is exhibiting any of the above conditions:

1. Take clear pictures of the water pump and connectors.
2. Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

LINK REFERENCES

This Tech Tip does not contain any link references